MATERIAL SAFETY DATA SHEET. CM_0167 HILLSBO PNT013)8 17123 PRODUCT NAME: ACRO LATEX ENAMEL (INT.SEMI-GLOSS) HMIS CODES: H F R P PRODUCT CODE: 2850 - 2898 1 0 Ω (WATER) MANUFACTURER'S NAME: MILLER PAINT CO., INC. ADDRESS: 12730 N.E. Whitaker Way, Portland, OR 97230 INFORMATION PHONE: (503) 255-0190 EMERGENCY PHONE: 1-800-424-9300 DATE REVISED : 03-25-91 NAME OF PREPARER : Buckinger/Serra ====== SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION ******* OCCUPATIONAL EXPOSURE LIMITS TAPOR PRESSURE WEIGHT HALARDOUS COMPONENTS CAS NUMBER OSEA THA ACCHE THA OSEA STEL IN ST & TOIP PERCENT *** NO REPORTABLE QUANTITIES OF HAZARDOOS INCREDIENTS ARE PRESENT *** *** No toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 🛱 🎆 ALL: -----SPECIFIC GRAVITY (H2O=1): BOILING RANGE: 212 - 340 Deg F 1.1 - 1 EVAPORATION RATE: SLOWER THAN ETHER VAPOR DENSITY: LIGHTER THAN AIR SOLUBILITY IN WATER: YES APPEARANCE AND ODOR: N/A ************* FLASH POINT: N/A FLAMMABLE LIMITS IN AIR BY VOLUME- LOWER: N/A **UPPER:** N/A EXTINGUISHING MEDIA: N/A SPECIAL FIREFIGHTING PROCEDURES people away. Bo not enter confined fire space without proper protective equipment including a NIOSE approved self-Lotained breathing apparatus. Cool closed containers with water. UNUSUAL FIRE AND EXPLOSION HAZARDS Closed containers may emplode when exposed to extreme heat. During emergency conditions, overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

(

STABILITY: STABLE CONDITIONS TO AVOID Note

INCOMPATIBILITY (MATERIALS TO AVOID)

HAZARDOUS DECOMPOSITION OR BYPRODUCTS

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

. .

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE Fapors or mists can cause drowsiness, cough, branchitis, blurred vision, irritation of means tenderses, muses, beadache, dissiness, reathess and loss of coordination.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE My cause initation.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE My cause irritation.

INGESTION HERLTH RISKS AND SYMPTOMS OF EXPOSURE hay cause headache, gastrointestinal irritation, nausea, romiting and distribut.

HEALTH HAZARDS (ACUTE AND CHRONIC) This product may contain some materials which at a normal low level should not present a problem.

CARCINOGENICITY: NTP? NO IARC MONOGRAPHS? NO OSHA REGULATED? NO

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE hay respiratory or skin condition my be approvated.

EMERGENCY AND FIRST AID PROCEDURES
Inhalation: Remove to fresh air.
Eyes: Flush immediately with water. Consult physician if irritation persists.
Skin: Remove with scap and water. Remove contaminated clothing.
Inspection: Brink 1 to 2 glasses of water to dilute. DO KOT induce romiting. Consult physician or poison control center immediately. Treat symptomatically.

3/27/91

PAGE 2 Of

4

PAGE 3 OE3

DEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED bey unnecessary people away. Ventilate enclosed spaces and avoid breathing vapors. Wear protective equipment, observing precautions on this sheet. Dike, contain and soak up spill with inert material (such as clay or sand).

WASTE DISPOSAL METHOD

Place in non-leaking containers, seal tightly and label properly for disposal. A health hazard may still exist since absorbent materials will only absorb liquid; they will not absorb wapors. Observe all federal, state and local regulations concerning disposal of hazardous waste.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Keep containers closed when not in use. Store and use only in well ventilated areas. Avoid breathing vapors or spray mist. Avoid eye or skin contact. Wash thoroughly after bandling. Never transfer material to an unlabeled container.

OTHER PRECAUTIONS

Read and observe precautions on product label and this sheet. Keep out of reach of children. 'Empty' containers may be hazardous from residues of product and vapor and all cautions of this sheet apply to them.

RESPIRATORY PROTECTION

None required under normal conditions. Filter recommended to remove solid airborne particles of overspray during spray application.

VENTILATION

Fot for use in confined areas. Use only with adequate ventilation.

PROTECTIVE GLOVES Home required under normal conditions.

EXE PROTECTION Face shield recommended for spray application.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT Kone required under normal conditions.

WORK/HYGIENIC PRACTICES Wash bands before eating, drinking, smoking or using the washroom.

DISCLAIMER

The information contained in this Material Safety Data Sheet is based on the data available to us and is believed to be correct. However, we assume no responsibility for any inaccuracies that may subsequently be proven. Purchaser assumes all risk in his use of the material even when recommended safety procedures are followed.

3/25/9

1